

WEEKLY INCIDENT SUMMARY

Week ending Friday 22 January 2021

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609, 24 hours a day, 7 days a week.

At a glance

High-level summary of emerging trends and our recommendations to operators. Please note the reportable incident total is recorded for the period 16 January 2021 to 22 January 2021.

TYPE	NUMBER
Reportable incident total	35
Summarised incident total	6

Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0039042 Underground coal mine	An operator was using a rib bolter when he was sprayed with hydraulic oil, under pressure. The worker was standing 1.2 metres away from the loose hydraulic fitting when the oil was released.	The mine has identified that the hose had come loose during operation, likely caused by spall material on the floor. Maintenance and inspection schemes should be designed to maintain work areas free of foreign material and to identify missing or defective guarding.
 Dangerous incident	A worker conducting electrical testing and tagging work has received an	Mine operators should seek every opportunity to apply the

IncNot0039050
Open cut coal
mine



electric shock when he contacted a float switch with a control circuit of 240V AC.

hierarchy of controls when managing electrical equipment in harsh environments.

The use of extra low voltage electrical equipment and field devices considerably reduces the risks associated with electric shock.

Where this control cannot be applied, the maintenance of the ingress protection (IP) rating for the electrical equipment should be paramount.

Dangerous
incident
IncNot0039053
Small mine

A worker, while attempting to attach his harness to a mobile crushing screen, has slipped and landed heavily on the ground. The worker sustained a fractured pelvis.

Mine operators are reminded that they have specific obligations under the WHS Regulations to manage the risk of a fall by a person. This includes having suitably rated attachment points for lanyards. Work positioning systems require a high level of competency on part of the user and supervisor to ensure safe use. Users should undertake competency-based training on work positioning systems. This training should include the selection of the correct harness and lanyard type. For more information about working at heights please refer to the Code of Practice, [Managing the risk of falls at workplaces](#).

Dangerous
incident
IncNot0039061
Underground coal
mine

While filling a void over a tailgate drive, a worker was sprayed with resin product when it released under pressure.

Safe work procedures for operating equipment under pressure should include provision for managing blockages and dissipation of pressure.



This is especially important when there is the potential for unexpected stored energy, associated with blockages, to be released without warning.

Dangerous incident
IncNot0039070
Open cut coal mine

An operator driving a fully loaded dump truck was descending a ramp when the truck has veered into a windrow and rolled onto its side.

Mine operators should reinforce the application of procedures, including fatigue management, use of mobile phones and compliance with speed signs.



Equipment operators must maintain situational awareness and remain vigilant of the risk of machine rollovers. This incident underpins the importance of wearing seatbelts as a mitigating control. When planning tasks and travel paths, supervisors must consider rollover hazards. [Refer to Safety Bulletin: SB17-01 Industry reports more truck rollover incidents](#)

Dangerous incident
IncNot0039071
Underground coal mine

A fire has occurred underground when an LHD has run over a battery-powered drill. The drill fell on the roadway after it was left on some poly pipe.

Mine operators should review their safety management system to ensure the risks associated with the use of battery powered portable electrical apparatus have been addressed. Risk assessments should consider:



- manufacturers safety information
- suitability of battery charging equipment and location
- transport and storage of batteries
- suitability of the equipment for the environment
- control of batteries in underground parts of the mine and hazardous areas including permit systems,

operator competency, chain of custody and transport and storage conditions.

- inspection regimes and regimes for removing batteries from service and lost or damaged equipment.

Resources Regulator publications

- [Safety Alert – SA21-01 – Elevated work box falls from integrated tool carrier](#)

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2021. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (January 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference DOC21/44825

Mine safety reference ISR21-03

Date published 29 January 2021

Approved by Acting Chief Inspector
Office of the Chief Inspector