

The incident

At about 8:30am on 26 February 2021, workers at the quarry were attempting to free a jammed hydraulic cylinder to lower the wing on a mobile jaw crusher.

The workers connected an 8-millimetre alloy sling grade T80 chain assembly (WLL rated at 3.5 tonne in straight lift) between the excavator and the crusher wing. During the task, the excavator was used to apply a sideways pull force to components of the hydraulic cylinder.


An uncontrolled release of energy occurred causing the chain assembly and components of the hydraulic cylinder to fail and a worker to sustain a serious laceration to an ear.

At the time of the incident, the injured worker is reported to have been located underneath the hopper operating the hydraulic controls of the mobile crusher. The worker sustained a serious laceration to an ear and was transported to the Mudgee Hospital for treatment.

Figure 1: Arrow pointing to the hydraulic cylinder (ram) that normally raises and lowers the wing of the crusher.



Figure 2: Failed chain components of the chain assembly used



The investigation

The NSW Resources Regulator has commenced an investigation to determine the cause and circumstances of the incident. The investigation is also examining alleged offences against an inspector by a quarry employee and compliance with requirements for safe storage and handling of explosives.

Safety Observations

Mine operators are reminded of their duty to identify hazards and manage risks to health and safety associated with the uncontrolled release of energy and lifting components.

Risk assessment processes that consider and apply risk controls in accordance with the hierarchy of controls must be undertaken, in consultation with all workers, prior to commencing unusual or infrequent work tasks.

When planning tasks involving lifting equipment, the WLL rating of the chain assembly and maximum pull/lift force (including potential for shock loading forces) that could be applied to the chain assembly, including selection of connection points, must be considered in a pull/lift system design.

Mine operators and workers must ensure safe standing zones are identified and established to account for potential component failure in the work system.

Further information

Please refer to the following guidance materials:

- [IIR20-09 Worker injured while conducting repairs to mobile jaw crusher](#)
- [IIR19-03 Worker injured releasing jammed conveyor chain](#)
- [Investigation report - Serious injury at Springvale Colliery 5 February 2019](#)
- [Lateral load shifting video](#)
- [Safety Alert SA18-05 Offsiders nose and cheek broken in incident](#)

About this information release

The Regulator has issued this information to draw attention to the occurrence of a serious incident in the mining industry. Further information may be published as it becomes available.

Visit our [website](#) to:

- learn more about our work on causal investigations and emergency response
- view our publications on other causal investigations.

© State of New South Wales through Regional NSW 2021. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (March 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference	DOC21/216014
Mine safety reference	IIR21-04
Date published	26 March 2021
Authorised by	Chief Investigator, Major Safety Investigations