

WEEKLY INCIDENT SUMMARY

Week ending Friday 19 March 2021

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of emerging trends and our recommendations to operators.

TYPE	NUMBER
Reportable incident total	42
Summarised incident total	3

Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0039443 Open cut coal mine  Roads or other vehicle operating areas	A dozer tipped on its side while in the process of levelling a windrow. The operator was able to exit the machine and sustained no injuries. 	Workers have a legislative duty to care for their own health and safety and that of others (s28 <i>Work Health and Safety Act 2011</i>). One of the duties is to cooperate with any reasonable policy or procedure. Failure to comply with a duty is an offence for which penalties apply. Site procedures are developed to help protect workers from injury or illness. Where a procedure exists for a particular task, workers should follow the procedure. Any deviation from a procedure should first be discussed with a supervisor and

Dangerous incident
IncNot0039450
Underground
metals mine



Ground or strata
failure

A fall of ground occurred across a haul road approximately 300 metres above the mine portal. Two operators were unable to drive out of the pit due to the ramp being blocked. There were no injuries.



appropriate risk control measures put in place.

Refer to safety bulletin [SB19-01 Rise in dozer incidents putting operators at risk.](#)

The fall of ground is currently being investigated and further information may be published at a later date.

The mine’s emergency plan must identify triggers for activation of the plan, actions to be taken and appropriate rescue equipment must be available.

For recommendations in relation to highwall failures, refer to safety bulletin:

[SB20-01 Failure of highwalls, low walls and dumps](#)

Dangerous incident
IncNot0039477
Underground
metals mine

A worker received an electric shock from an air conditioner controller switch that was housed in a weather-proof enclosure. The subsequent investigation found that the IP rating of the switch did not meet the site standards.



Mine operators are reminded of the need to follow introduction to site procedures to ensure second-hand equipment meets the required standards. The [Electrical Engineering Control Plan Code of Practice](#), (1.6.8 Acquisition of Plant) states that “the EECPP should provide systems to ensure the acquisition of plant includes the processes to verify that any plant, new to the mine, is fit for the intended purpose in the intended operating environment and is safe to use (introduction to mine site).”

Other Resources Regulator publications

Safety Bulletin [SB21-01 – Refuelling fires](#)

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
	International (fatal)
MSHA	<p>Mine fatality</p> <p>On 5 March 2021, a miner was fatally injured when the excavator he was operating rolled over into a body of water.</p> <p>Details</p>
	International (other, non-fatal)
MinEx NZ	<p>Rockfall damages excavator</p> <p>While an excavator was working at the toe of a bench, a rock fell out of the face hitting the excavator. The excavator was damaged, but no injuries were sustained by the operator.</p> <p>Details</p>
	National (other, non-fatal)
DMIRS	<p>Radiator blades seriously injure mechanics hand; Significant Incident Report #284</p> <p>A service mechanic had just completed a general service of a 300 kVA generator, de-isolated it and brought it back online. He then conducted post service inspection and clean up, including wiping oil and grease marks with a rag.</p> <p>When the mechanic leaned into the generator enclosure, with the rag in his hand, it appears the rag and hand, were drawn into the rotating radiator fan blades, causing serious injuries.</p> <p>Details</p>

DMIRS Hazards associated with use of e-cigarette devices; Mines Safety Bulletin #181

There was a report of an incident where an electronic cigarette (ape) battery spontaneously ignited in his pocket, while he was travelling in a ute with two other workers.

[Details](#)

DMIRS Competency of spotters during mobile load shifting operations; Mines Safety Bulletin #182

Spotters can be an effective control for reducing the risk of inadvertent impact by operators of mobile load shifting equipment. It is important that they have the necessary knowledge, skills and experience to do so competently.

[Details](#)

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2021 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (March 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference DOC21/221385

Mine safety reference ISR21-11

Date published 26 March 2021

Approved by Deputy Chief Inspector
Office of the Chief Inspector