



# **WEEKLY INCIDENT SUMMARY**

## Week ending Friday 28 January 2022

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

### At a glance

High level summary of emerging trends and our recommendations to operators.

ТҮРЕ	NUMBER
Reportable incident total	23
Summarised incident total	2

### **Summarised incidents**

#### **INCIDENT TYPE SUMMARY COMMENTS TO INDUSTRY** A blast hole prematurely detonated This incident is under Dangerous incident while preparing for a shot. There were investigation and further IncNot0041475 eight personnel on foot and an information may be published Open cut coal additional three within machinery on the later. Mine operators must have Fire or explosion procedures when loading hot and The minimum distance between the hole reactive ground. Procedures must and personnel was about 100m. The shot include timeliness of loading and hole was loaded on the day of the firing and the control of persons incident and recorded at 34-degree on the shot. Adequate Celsius. One hour after the hole was supervision must be in place to loaded with emulsion, it prematurely ensure compliance to shot firing detonated. procedures.



Dangerous incident IncNot0041247 Underground metals A Jumbo offsider suffered an electric shock while in contact with both the Jumbo and the rib mesh. The offsider suffered the shock when the electrical supply to the machine was restored after moving the Jumbo forward.

The electrical engineering control plan for a mine must set out the control measures to manage risks to health and safety from electricity at each mine. When developing the control plan all sources of electrical sources need to be considered including induced and static charge.

Refer to Safety Bulletin
SB20-03 Electric shocks in the
mining industry

## Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
	National (other, non-fatal)
DMIRS (WA)	Damaged excavator recoil spring fragment became projectile – Significant Incident Report #289
	In February 2021, a damaged recoil spring assembly for an excavator had been removed from the track arrangement and stored outside a heavy mobile plant workshop. The following morning, a fragment of the spring separated while under



compression and travelled approximately 28 metres across the yard and through a workshop wall, coming to rest in a walkway beside a workbench.

**Details** 

### **DMIRS (WA)**

#### Company fined after worker was seriously injured

BHP Iron Ore Pty Ltd was fined \$125,000 after a contractor suffered a lacerated artery from being struck in the neck by a metal shard in September 2017.

**Details** 

### Resources Safety and Health, Queensland (Coal)

# Managing exposure to heat in surface coal mines and surface areas of underground coal mines – Guidance note QGN32

The purpose of this guidance note is to provide practical guidance to coal mine operators, employers and employees about how to manage heat exposure at open cut coal mines and on surface areas of underground coal mines, in order to prevent heat-related illness.

**Details** 

**Note:** While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2022 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (January 2022) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL	
CM9 reference	RDOC22/12375
Mine safety reference	ISR22-04
Date published	9 February 2022
Approved by	Deputy Chief Inspector Office of the Chief Inspector