

WEEKLY INCIDENT SUMMARY

Week ending Friday 7 October 2022

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of emerging trends and our recommendations to operators.

TYPE	NUMBER
Reportable incident total	38
Summarised incident total	6

Summarised incidents


INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0043138 Underground metals mine Ground or strata 	A rock burst occurred in an underground metals mine. A drill rig was working in the area but the operator was not affected. A seismic event with a magnitude of 1.4 was measured at the mine. The mine operator stopped work, barricaded the area and commenced monitoring.	Mine operators are reminded of the update to the Work Health and Safety (Mines and Petroleum Sites) Regulation 2022 Schedule 1 Section 1(1)(x) where mine operators must consider the risk of rock, coal or related pressure burst as part of the PHMP for ground and strata failure.



Dangerous incident
IncNot0043177
Underground coal
mine
Ground or strata



An electrician was cleaning a proxy sensor on a conveyor roller when their finger was caught between the sensor and the roller. The worker suffered a fractured finger, lost the fingernail and suffered soft tissue damage. The injury required surgery.



Workers should never place their hands or fingers near rotating components.
When a task involves working near rotating components, the equipment must be isolated first.

Dangerous incident
IncNot0043142
Underground
metals mine
Fire or explosion

An ice machine located near an underground crib room caught fire due to a faulty electrical connection. The fire was extinguished with a hand-held fire extinguisher.

Mine operators must have documented life-cycle maintenance strategies for plant and ensure that maintenance is undertaken in accordance with the manufacturer's recommendations.
Regular inspections and testing must be carried out on all equipment.



Dangerous incident
IncNot0043153
Open cut coal mine
Fire or explosion



A dozer operator jumped from the deck to the ground to escape flames when the dozer caught fire. The worker saw smoke and flames emanating from the left and right engine bay doors. As the worker tried to activate the fire suppression system from within the cab, the switch unit came away from the panel and couldn't be activated. The worker reversed the dozer to level ground so they could egress safely. When the worker tried to egress, the ladder was impeded by smoke and flames so the worker jumped from the deck to the ground. The worker was uninjured. The investigation identified that the safety clip was looped behind the activation handle. This prevented the safety clip from being able to be removed. The dozer was a hire plant that had a different activation method for the fire suppression system to those fitted other dozers on the site.


Operability of fire suppression systems in the event of a fire emergency is critical to the health and safety of operators on mobile plant. Inspections should confirm that fire suppression systems can be quickly activated. Mine operators should review second egress methods and regularly train workers in their location and use. Mine operators should ensure that change management processes identify the differences between new plant introduced to site and existing plant in use at the site.



Dangerous incident
IncNot0043166
Open cut coal mine
Roads or other
vehicle operating
areas



An articulated dump truck was travelling around a right-hand corner when the rear tyre contacted the middle delineation island and tipped the tub onto its side. The cab remained upright and the operator was not injured.



The stability of articulated trucks is a known risk that should be managed at mines. Factors that truck operators must consider include (but are not limited to):

- speed of operation
- operating grades
- uneven surfaces (holes, rocks, foreign material)
- tipping of loads
- hang-up of loads
- movement of loads.

The risks associated with the rollover of mobile plant was the subject of our compliance priority program in 2018. Refer to the following outcome report for more information:

[Articulated truck rollovers and falls from mobile plant](#)

Refer to Safety Bulletins:

[SB17-01 Industry reports more truck rollovers](#)

[SB18-07 Safe systems of work for mobile plant](#)

Dangerous incident
IncNot0043177
Underground coal
mine
Ground or strata



A slab of coal on the longwall fell forward onto the ranging arm, slid down the arm, spilling over the pan line and struck a worker on the ankle knocking them over. The worker was standing on the front walkway of the roof supports. The shearer was entering the snake in the tailgate. Cutting was done in compliance with the restricted zone limits.



Mine operators should consider flyrock and slabbing strata risks when determining restricted access zones for operators on longwalls. When reviewing controls related to a principal hazard, the impacts from all principal hazards must be considered.

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
National (other, non-fatal)	
WA Department of Mines, Industry Regulation and Safety	Mines are required to have a risk-based procedure in place for managing breakthroughs when workings being developed and long holes or exploration holes being bored are approaching an area where other work may be occurring. A drilling procedure checklist should be developed with input and scrutiny from all management departments. Develop the required safety instructions, including the breakthrough control requirements and any plan showing the drilling location and all the underground drives in the vicinity which need to be isolated or barricaded. Surveyors must check the current and historic underground plans for the mine to identify all potential breakthrough areas and carry out any check surveys needed to confirm the position of all areas and locations where a breakthrough is likely to occur.

[Read more](#)

Note: While most incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2022 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (October 2022) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference	DOC22/285366
Mine safety reference	ISR22-40
Date published	14 October 2022
Approved by	Deputy Chief Inspector Office of the Chief Inspector