

Weekly incident summary

Week ending 13 January 2023

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of emerging trends and our recommendations to operators.

Type	Number
Reportable incident total	30
Summarised incident total	4

Summarised incidents

Incident type	Summary	Comments to industry
Dangerous incident IncNot0043849 Underground coal Roads or other vehicle operating areas 	While positioning a large air conditioner unit on top of a transformer, a worker suffered a serious finger laceration that required surgery.	When large components are being moved or positioned by workers, suitable mechanical aids and task-sequencing should be used to reduce the workers' exposure to pinch points and manual handling injuries.
Dangerous incident IncNot0043846 Underground coal	A worker was struck on the head and shoulder by a falling pallet that was stacked with diesel particulate filters. One pallet had been stacked on another and other workers had been removing filters from the lower pallet.	Mines should review their practices for stacking filters and other consumables. Workers must consider the stability of stacked pallets when removing items so as not to pose a hazard to other workers.

Weekly incident summary week ending 13 January 2023

Incident type	Summary	Comments to industry
		
<p>High potential incident IncNot0043845 Mineral sands Fire or explosion</p> 	<p>A large tractor was working on rehab carting topsoil. Fluid sprayed from the engine bay over the windscreen and shortly after flames appeared around the engine. The operator received minor burns to their wrist and was taken to hospital for assessment. Several nearby workers immediately rendered assistance and attempted to extinguish the fire.</p> <p>The workers were unable to directly raise the emergency and relied on another worker to relay the emergency message.</p> <p>The mine's emergency response team responded with a fire tender, and water carts were used to extinguish the fire.</p> <p>The tractor was destroyed.</p> 	<p>An investigation into this incident has commenced and further information may be released in the future.</p> <p>Mines must ensure all work groups have suitable means to raise emergencies, including when working in isolated or locations remote from mine infrastructure.</p>

Weekly incident summary week ending 13 January 2023

Incident type	Summary	Comments to industry
<p data-bbox="124 880 323 1137">High potential incident IncNot0043811 Open cut coal Roads or other vehicle operating areas</p> 	 <p data-bbox="400 880 991 1261">The operator of a loaded haul truck was using a two-way radio while descending a ramp. The operator failed to control the speed of the truck and could not stop. The operator drove through an intersection and into a flat park-up area beside a crib room. The truck was safely brought to a stop. Another truck was approaching the intersection and was 40 metres away, no other workers or vehicles were in the park-up area.</p> <p data-bbox="400 1272 991 1346">The worker had only recently been deemed competent to operate a haul truck.</p>	<p data-bbox="1038 880 1453 1155">When operating machinery, workers' primary focus must remain on the operation and control of the plant or vehicle. Interactions with radios, dispatch systems and vehicle controls should only occur when safe to do so.</p> <p data-bbox="1038 1167 1453 1379">Mines should review the triggers for competency assessment and the minimum level of competence required before workers are authorised for solo operations.</p>

Note: Please ensure all relevant people in your organisation receive a copy of this safety alert and are informed of its content and recommendations. This safety alert should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's common area, such as your notice board where appropriate.

Visit our [website](#) to:

- find more safety alerts and bulletins
- use our searchable safety database

If you are required to insert an image, make sure you include a caption. Position the image where it is required, right-click the image and click Insert Caption. Type your caption following the figure number, for position select below image and click OK. See example below.

Weekly incident summary week ending 13 January 2023

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	National (other, non-fatal)
Resources Safety & Health Queensland	<p>On 27 July 2020 two coal mine workers (CMWs) received serious injuries from rib spall while working on a continuous miner (CM) in an underground development panel heading. The incident occurred as the CMWs were installing roof support and extending ventilation tubes. The Inspectorate's investigation into the incident identified that the rib protection installed on the fleet of CM did not provide effective protection from rib spall to CMWs and the mine had a fleet of three CM supported by two different original equipment manufacturers.</p> <p>Read more</p>

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2023. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (January 2023) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Document control	
CM9 reference	RDOC23/3593
Mine safety reference	ISR23-02
Date published	20 01 2023
Authorised by	Deputy Chief Inspector Office of the Chief Inspector