

Weekly incident summary

Week ending 18 Aug 2023

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of emerging trends and our recommendations to operators.

Туре	Number
Reportable incident total	44
Summarised incident total	4

Summarised incidents

Incident type	Summary	Comments to industry
Dangerous incident IncNot0045258 Open cut coal Roads or other vehicle operating areas	<text><text></text></text>	Workers must operate vehicles at a speed that is appropriate to the prevailing conditions. Engineering controls that minimise the risk of loss of control should be considered, including the use of speed-limiting devices, speed monitoring and alarms. This incident highlights the importance of having appropriately designed and maintained windrows, bunds and edge protection.

Weekly incident summary week ending 18 Aug 2023

Incident type	Summary	Comments to industry
Dangerous incident IncNot0045232 Open cut coal Ground or strata failure	<text><text></text></text>	Mine operators should ensure their high wall TARPs include controls in relation to unchained walls, wet weather and the combination of the two factors. Mine operators should review systems for recording and communicating to operators which walls are yet to be chained.
Dangerous incident IncNot0045239 Underground coal Leave blank	A continuous miner was cutting a plunge when the operator noticed smoke coming from the area around the cable handler. The machine was flitted back when they heard a pop and saw a flash. Upon inspection, an electrical arc had occurred leaving visible evidence of arcing. The electrical protection did not operate.	Electrical protection systems must be maintained to ensure they operate correctly when a fault occurs. Protection settings need to be aligned with the site protection study. Good maintenance practices must be in place to ensure that cables are used and maintained as per site cable standards.
Dangerous incident IncNot0045242 Open cut coal Roads or other vehicle operating areas	<text><text></text></text>	Mine operators should conduct a change management process for the operation of trucks fitted with tailgates when they are used to haul material other than the material the truck and dump body were designed for.

Weekly incident summary week ending 18 Aug 2023

Other Resources Regulator news

Have your say - Discussion paper - vehicle interaction controls in NSW mines

Reminder for stakeholders to have their say and provide valuable feedback on the Vehicle Interaction Control Discussion Paper. This feedback will help the Resources Regulator address adverse vehicle interactions in the NSW mining industry.

Consultation is open until 5pm, Friday 8 September 2023.

You can read the paper here: Vehicle interaction controls in underground mines.

To provide your feedback visit resourcesregulator.nsw.gov.au/public-consultation.

For media inquiries or further information, please contact meg.media@regional.nsw.gov.au.

Other publications of interest

These incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	National (other, non-fatal)
Resources Safety & Health Queensland	Resources Safety and Health Queensland is cracking down on Queensland coal mines that are failing to protect workers from dozer rollover incidents. The industry's independent safety regulator will be targeting mines and suspending operations when the risk is not at an acceptable level, after noticing an increase in bulldozer rollovers, including two in the past week. There have been 19 dozer rollover incidents from January 2022 to August 2023.
	Incident 1: On 7 August 2023 a Coal Mine Worker (CMW) in Blackwater was required to push high waste material down using a CAT D11T Dozer to allow for the safe excavation of material using a large hydraulic excavator. Prior to executing the task, the work area inspections had not identified the hazards present which included an over-steepened excavated face on the high wall, the substandard berms in place, and the steps required to safely complete the task.
	Incident 2: On 8 August 2023, a CMW in Isaac Plains was in the process of marking out the dig limits for an excavator double benching in the area with a CAT D10T dozer. The coal mine worker identified the area had no edge protection berms in place and did not manage the risk associated with this hazard. While reversing towards the edge, without the edge protection berm, the dozer has breached the open edge and rolled approximately 110 degrees to the bottom of the slope.
	Details

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2023. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (August 2023) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Weekly incident summary week ending 18 Aug 2023

Document control	
CM9 reference	RDOC23/238029
Mine safety reference	ISR23-32
Date published	25 August 2023
Authorised by	Director Regulatory Operations Mine Safety Office of the Chief Inspector