SAFETY ALERT



MINE SAFETY

A BRANCH OF THE NEW SOUTH WALES DEPARTMENT OF PRIMARY INDUSTRIES

ELECTRIC SHOCK FROM CIRCUIT BREAKER

INCIDENT

An electrician received an electric shock when he made direct contact with the load side terminals of a moulded case circuit breaker.

CIRCUMSTANCES

The circuit breaker was indicating that it was in the "OFF" state. The electrician was planning the installation of cables to the circuit breaker when his hand made contact with the exposed load side terminals. These terminals were found to be energised at three phase 415V.



INVESTIGATION

The circuit breaker had previously been dismantled to fit an internal accessory. The circuit breaker appears to have been incorrectly reassembled.

The label showing "OFF" and "ON" had been fitted in reverse. Whenever the circuit breaker was indicating "OFF", it was in fact closed.

RECOMMENDATIONS

1. All operations should have a "Test Before Touch" policy.

2. The policy should ensure that electricity workers prove circuits are de-energised before working in proximity to them by using a fit for purpose multi meter and / or non contact voltage detecting device.

3.All operations should review commissioning procedures for electrical installations to ensure that commissioning tests are conducted for new, modified and repaired installations in accordance with relevant legislation and standards.

R Regan CHIEF INSPECTOR OF MINES CHIEF INSPECTOR OF COAL MINES

Find Safety Alerts at: http://www.minerals.nsw.gov.au/safety/safalert.htm

Report No: SA 04 10 File No: 04/1631 Comet ID: 31889000_314318000 Prepared by: Steve Millington Phone: 0265 721 899 Date Created: 01/07/04 14:56