

NSW Minerals Industry OHS Conference 2008

Stream - Equipment Design

A case study of two NSW DPI incident investigations and the results from testing conducted on a winder haulage rope and chain components


Tony Smith - Senior Investigator NSW DPI

Wally Koppe – Inspector of Mechanical Engineering NSW DPI




Case Study One – Failure of a Winder Haulage Rope

- Incident Date 6 May 1999 the 52mm drift haulage rope broke after being in service for 15 months
- Rope rated at 1828kN (186 tonnes)
- 80 t capacity winding system



Failed Haulage Rope



Consequence of Failed Rope



Consequence of Failed Rope



Longwall chock
 chock carrier
 MPV travelled
 40m from flat top

Tyre tread cut from tyre casing
 as ejected from flat top



- Non destructive testing
 - Inbye 90m of rope NDT
 - Outbye rope NDT examined at wire rope plant

- LMA is not directly proportional to actual loss of strength

- Outer wires contribute 57% to 66% of total strength of wire rope



Photograph No. D26 – NDT set-up

- Destructive testing
 - Resin end testing
 - Grip testing

- Relationship between NDT measured LMA and loss of actual strength

- Effects of obstructions in drift were clear




Photo No. 1Y/1 - Rope sample before testing



Phot No. 1Y/2- Rope sample after testing


Destructive Test Results



Breaking Force Vs LMA

**Breaking Force Vs Loss of Metallic Area
Relative to Position in Rope**

◆ Breaking Force
◆ %LMA



- **Rope Diameter Measurements**
 - Using diameter loss to identify strength is not considered accurate
 - Significant diameter loss may occur after being placed in service due to bedding of rope components

- **Individual Wire examination and Analysis**
 - New rope and 8 samples of broken rope were chemically and microstructure analysed
 - Individual wires tested for tensile strength, torsion and reverse bend cycles as per AS 3569-1989


- Publicise the DPI report
- Encourage regular audits of winders and wire ropes by experts
- AS 4812 was published in 2003.
- Encourage use of auto systems to limit maximum loads on ropes to an envelope suitable for the load.

Case Study Two

Failure of a Chain Connector

- Incident Date 28 May 2004
- Underground coal mine installing a longwall
- Two 1.8m length chain sets reeved around a longwall shearer ranging arm
- 20mm herc alloy chain assembly failed at the connector
- Connector placed in side loading
- Components rated at WLL 9.8 tonne in reeved pull

Chain connectors placed in side pull



Post
incident

simulation
of Chain
connector in
side pull


1 JUN 2004

Effective forces at time of incident

**36 tonne max.
pull by shearer**

Chain sling assembly
WLL of 9.8 tonne
in a reeved pull

Maingate
Drive Unit



Tailgate
Free to rotate

Tailgate
Drive Unit

Partially loaded AFC

**Chain
Component
Failure**

Resistance of 269 tonnes

Maingate drive held
Stationary by brake system
1320 kN per strand

Connector straight pull test


Straight
Pull
Test



- Ultimate load 470kN 47.9 tonnes
- Pin sheared into 4 pieces
- Legs intact and deformed

Connector side pull test

Side
Pull
Test



Connector arm failed.
Similar failure mode to
connector involved in
the incident

- Ultimate load 236kN 24.1 tonnes
- Failed connector body near eye
- 52% less than AS 3766-1990 requirement (in straight pull)

- Standards of Mechanical Engineering practice
- Supervision and training
- Fatigue management
- Original Equipment Manufacturers (OEM) and Suppliers of Lifting and Pulling Mining Equipment

- Chain sling arrangements in Australian Standards to be modified to reflect best practise .
- *“Assemble only one chain or fitting to each Hammerlock type body half.”*
- Identify working load limits (WLL) of all lifting and pulling equipment

- Development of a mining industry certified competency based training course.
- Ensure clear lines of authority
- Contractor Management systems to clearly define the scope of work and supervisory role of the contractor.

- OEM to assemble chains with only one load bearing component on any one end of a connector
- OEM/Suppliers to supply adequate instructional documentation for assembly, installation and safe use of equipment supplied.
- OEM/Suppliers to identify pulling forces and weight of equipment supplied.

When mines are preparing lifting and pulling work procedures they should take the opportunity to:

- ensure compliance with Working Load Limit (WLL) of pulling and lifting equipment.
- ensure information is readily available at the work site to identify forces applied to pulling and lifting equipment.
- ensure a competent person supervises and takes responsibility for all pulling and lifting tasks.

- Safety Alerts published for both incidents
- Conducted an industry seminar on winder systems
- Ongoing Audit of powered winding systems through to 2009
- Consultation with Australian Standards Committees, OEM's and mining industry
- Legislative changes incorporating design and plant registration for winding systems

- CD available free of charge
- CD contains all reports
- Contact DPI publications – Maitland
- www.dpi.nsw.gov.au/minerals/safety