

# WEEKLY INCIDENT SUMMARY

Week ending Friday 9 July 2021

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.


## At a glance

High level summary of emerging trends and our recommendations to operators.

TYPE	NUMBER
Reportable incident total	18
Summarised incident total	1

## Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0040269 Surface mine	A watercart passed through the site wheel wash enclosure and travelled down a sealed asphalt ramp towards the weigh bridge. The watercart was spraying the ramp to remove a build-up of dirt and silt that had dropped from vehicles using the ramp. The operator lost control of the watercart and tried to brake and steer it into the bank but couldn't stop. It then collided with a truck and dog trailer waiting on the weighbridge. The operator had mistakenly assumed the truck was in the process of exiting the weighbridge when he began his descent. The traffic control lights for the ramp were inoperable at the time. There were no injuries.	Mine operators should ensure traffic control devices are working as per design. Vehicle operators should always seek positive communication and should never assume the movement of another vehicle. Operators are reminded to always drive to conditions.



## Other publications of interest

These incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
	<b>International (fatal)</b>
<b>MSHA</b>	<b>Mine fatalities</b> - On 9 June 2021, two mine workers were fatally injured when a locomotive collided with the personnel carrier in which they were riding. <a href="#">Details</a>

**Marine Safety  
Forum**

**Danger of older/damaged extinguishers - Fatality**

A worker discharged a corroded handheld cartridge-type, dry chemical powder fire extinguisher, which had been condemned during an annual third-party inspection. When the internal carbon dioxide cylinder was activated to energise the fire extinguisher, the unit ruptured at the corroded base, exploded, and struck the worker, causing critical head injuries.

[Details](#)

**MinEx NZ**

**Quarry fatality – Rockfall**

Falls of ground/rock are a major cause of fatalities in the extractives sector, both in New Zealand and internationally. A worker was fatally injured when a rock fell onto an excavator during its operation. The precise details have not yet been released and are still under investigation.

[Details](#)

**Note:** While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2021 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (July 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

**DOCUMENT CONTROL**

**CM9 reference** DOC21/584046

**Mine safety reference** ISR21-27

**Date published** 16 July 2021

**Approved by** Deputy Chief Inspector  
Office of the Chief Inspector