

# NSW Resources Regulator

# WEEKLY INCIDENT SUMMARY

Week ending Friday 3 December 2021

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

# At a glance

High level summary of emerging trends and our recommendations to operators.

ТҮРЕ	NUMBER
Reportable incident total	31
Summarised incident total	4

# **Summarised incidents**

**INCIDENT TYPE SUMMARY** COMMENTS TO INDUSTRY A haul truck was travelling adjacent to an This incident is under **Dangerous** incident office complex and car park. The position investigation. More information IncNot0041198 five tyre failed, causing stones to be may be published at a later date. Surface coal thrown towards the office complex and car park. A window was broken and a golf ball-sized rock landed near a person in the car park. There were no injuries.


#### WEEKLY INCIDENT SUMMARY

Week ending Friday 12 November 2021

## NSW Resources Regulator

### Dangerous incident IncNot0041189 Metals

A worker was driving a light vehicle on an access road when the steering failed. The vehicle veered left and came to rest in an adjacent drainage channel. The vehicle was travelling about 40 kph. The worker was uninjured.



The operating environment of vehicles must be considered when developing maintenance strategies for component inspection and replacement.

High potential incident IncNot0041188 Metals A storm front moved over a mine resulting in more than 100 mm of rain falling within 30 minutes. A creek between the open cut pit and dump burst its banks and flowed into the pit. No workers were in the mine at the time. Refer to <u>SB21-10 Summer –</u> severe weather season



#### WEEKLY INCIDENT SUMMARY

Week ending Friday 12 November 2021

## NSW Resources Regulator

Explosives incident IncNot0041180 Metals A mobile processing unit (MPU) was transported offsite for maintenance. Three days later, an inspection of the pump cabinet at the maintenance facility offsite identified emulsion was present. Inspections identified half a tank of emulsion and half a tank of gassing agent where still onboard. No AN locks were in place on the tank or cabinet. The truck was returned to the mine.

This incident is being investigated by SafeWork NSW. However, this incident is a timely reminder for mine operators to have a robust system in place to ensure all equipment is fit to leave the site.

# **Resources Regulator publications**

• SB21-12 Be safe this festive season

# **Other publications of interest**

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
	International (fatal)
MHSA	Mine fatality – On 17 November, 2021, a customer truck driver was electrocuted after the tarping mechanism on the trailer made contact with a high-voltage overhead power line. While exiting the cab of the truck, the worker made contact with the energised truck and suffered a non-fatal electrical shock. When he tried to re-enter the cab of the truck, he was electrocuted. Details
	International (other, non-fatal)
Energy Safety Canada	Safety Alert #15-2021 Valve falls from height striking and seriously injuring a worker - While reciprocating casing during a cement job on a drill rig, a valve weighing greater than 15 kg broke off at the threaded nipple union and fell approximately 5 to 6 metres, striking a worker in the leg and causing serious injury. Details

### WEEKLY INCIDENT SUMMARY

Week ending Friday 12 November 2021

## NSW Resources Regulator

#### National (other, non-fatal)

SafeWork SA

#### Unlicensed operator tips vehicle

SafeWork SA is issuing a safety alert to remind PCBUs that they must not direct or allow a worker to carry out work activities without holding the relevant high-risk work licence following an incident involving a vehicle loading crane.

<u>Details</u>

**Note:** While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 202 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (December 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL	
CM9 reference	DOC21/1084422
Mine safety reference	ISR21-48
Date published	10 December 2021
Approved by	Deputy Chief Inspector
	Office of the Chief Inspector