



REPORTABLE INCIDENTS | WHS MINES LEGISLATION

Weekly incident summary

Published 6 April 2016

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week and summarised in this report. For more comprehensive statistical data refer to our Annual Performance Measures Reports.

Reportable incidents total

Level 1 incidents	Level 2 incidents	 Level 3 incidents
76	5	0

Note: Incidents are categorised as Level 1, 2 or 3 according to the seriousness of the incident, with 3 being the most serious.


Injuries	Fatalities
13	0

Reportable incidents overview

Note: While all incidents are investigated, generally only level 2 and 3 incidents are summarised below.

Tyote. Write all induction are investigated, generally only level 2 and 3 including are summanised below.					
Level	Incident type	Summary	Comment to industry		
2	Work environment (complaint) 317659739001	Safety complaint regarding lack of fencing and accessible steep decline between land owner and mine site.	Complaint being investigated by Mine Safety.		
2	Electrical energy 317659882001	Shuttle car cable damaged when outrigger made contact with the rib. The shuttle car was dumping coal in a cutthrough at the time of the incident.	Operators are reminded that whenever changes to work practices are made, an assessment of risks must be undertaken so that any new hazards are identified and effective controls are put in place prior to commencing work.		
2	Work environment 317659757001	Operator slipped off the bolting platform on a continuous miner and injured ankle.	Mines should assess risk of slipping from work platforms including consideration of the height of kick-boards and positioning of hand-rails.		
2	Electrical energy 317659906001	Low voltage electric shock to two people occurred after coming into contact with an exposed wire on a lighting cable.	When installing lights, or other electrical apparatus, consideration must be given to the location of cables with respect to pinch points or exposed areas with the potential for damage.		

Level	Incident type	Summary	Comment to industry
2	Explosives 317659846001	An investigation was conducted at a mine as a result of explosives found by an external agency at an ex-mine employee's house.	Mines should regularly audit compliance against the mine explosives security plan.
			Particular focus to be directed at stock reconciliation, authorised access to explosives, detonators and explosives precursors.
		The investigation at the mine did not identify any evidence in relation to this matter.	
			Metalliferous and extractives mines may refer to MEX-01: Explosive management system audit checklist for metalliferous and extractive mines and quarries.
		No action was required at the mine.	
			The SafeWork NSW Security plan guide is also a relevant reference.



Recent incident publications

No recent incident publications

You can find all our incident related publications (i.e. safety alerts, safety bulletins, incident information releases, weekly incident summaries and investigation reports) on our <u>website</u>.

2 NSW Mine Safety ISR16-13 Published 6/04/2016

Further information

Should you wish to seek further information, please contact one of our offices:

COAL (NORTH) and EAST METEX Maitland

NSW Department of Industry Mineral Resources 516 High Street, Maitland NSW 2320 (PO Box 344, Hunter Region MC NSW 2310) T 1300 736 122 or 02 4931 6666

F 02 4931 6790

E mine.safety@industry.nsw.gov.au

COAL (SOUTH)

Wollongong

NSW Department of Industry State Government Offices Level 3, Block F, 84 Crown Street, Wollongong NSW 2500 (PO Box 674, Wollongong NSW 2520)

T 02 4222 8333 F 02 4226 3851

WEST METEX

Orange

NSW Department of Industry 161 Kite Street, Orange NSW 2800 (Locked Bag 21, Orange NSW 2800) T 02 6360 5333 F 02 6360 5363 After hours - emergency only 02 6360 5343

© State of New South Wales through the Department of Industry, Skills and Regional Development 2015. You may copy, distribute and otherwise freely deal with this publication for any purpose, provided that you attribute the NSW Department of Industry, Skills and Regional Development as the owner.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (April 2016). However, because of advances in knowledge, users are reminded of the need to ensure that information upon which they rely is up to date and to check currency of the information with the appropriate officer of the NSW Department of Industry, Skills and Regional Development or the user's independent advisor.

3 NSW Mine Safety ISR16-13 Published 6/04/2016