# Mine safety performance overview




#### **Metalliferous mine**


On 12 August 2019, a contract worker suffered fatal injuries following an interaction between a light vehicle and dozer at a surface metalliferous mine. The contract worker was driving a light vehicle and entered the tip head area to deliver a water bottle to a dozer operator at about 4:45pm. The dozer operator was reversing and was unaware the light vehicle was in close proximity. The two vehicles collided, resulting in fatal injuries to the light vehicle driver.

See Investigation Information Release IIR19-11 for more information.


# Serious injuries 106 INCREASE OF 12 IN 2019-2020 -

For a detailed review of serious injuries and illnesses including bodily location, nature, mechanism and employment type refer to the 2019-20 <u>report</u> on our website.





### Mine safety performance overview




per

0

Underground

Surface



**EXPLORATION** 

SITES

OPAL

MINES

9


2



- Medical treatment injury/illness
- Other incident notification

FY 2012 FY 2013 FY 2014 FY 2015 FY 2016 FY 2017 FY 2018 FY 2019 FY 2020

#### Mine safety performance overview



#### **For more information**

This overview was first published in June 2021 with data current at March 2021.

To read the full <u>Mine Safety Performance Report for 2019 - 2020</u>, and other safety publications, visit our <u>website</u>.

© State of New South Wales through Regional NSW 2021. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a departmental website. Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (June 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publicatior.

