



**NSW
Resources
Regulator**

MONTHLY BUSINESS ACTIVITIES REPORT

March

2020



Document control

Published by NSW Department of Regional NSW, NSW Resources Regulator

Title: Monthly business activities report – March 2020

First published: April 2020 (data current at 3 April 2020)

Authorised by: Executive Director Resources Regulator

CM9 reference: DOC20/326218-1

© State of New South Wales through the NSW Department of Regional NSW 2020.

This publication is copyright. You may download, display, print and reproduce this material in an unaltered form only (retaining this notice) for your personal use or for non-commercial use within your organisation. To copy, adapt, publish, distribute or commercialise any of this publication you will need to seek permission from the NSW Department of Regional NSW.


Disclaimer: The data in this report was extracted from the NSW Resources Regulator's compliance database on **3 April 2020**. However, users are reminded that since then, new information may have been received. If you are concerned about the currency of any of the information in the report, please check with the appropriate officer at the NSW Department of Regional NSW.

Contents

Activities at a glance	4
Key enforcement actions	5
Safety incidents of note	5
Work health and safety activities	6
Safety incident notifications	6
Safety assessments	7
Safety compliance activities	10
Safety mining competencies activities.....	13
Mining Act regulatory activities.....	15
Mining Act statutory notices.....	15
Security deposit reviews	17
Safety legislation and Mining Act notified compliance concerns.....	18
Safety compliance concerns	18
Mining Act compliance concerns	19
Industry engagement activities	20
Committees and other industry body involvement.....	20
External education and engagement activities	21
Publications and alerts.....	22

Activities at a glance

SUMMARY OF OUR REGULATORY ACTIVITIES MARCH 2020



Key enforcement actions

The Resources Regulator has commenced [prosecution proceedings](#) against Young Mining Pty Ltd as the operator of Thuddungra mine for alleged contraventions of the WHS Act relating to the alleged non-compliance with one prohibition and eight improvement notices issued to the company.

Safety incidents of note



Fire or Explosion: A front end loader caught fire at an open cut quarry resulting in extensive damage. Prior to the fire, oil was observed on the ground by another mobile plant operator. A short time later the front-end loader caught fire and the operator was alerted. The fire suppression system and a water cart were used to extinguish the flames. No one was injured. The cause of this fire has not yet been established.

For further information refer to the dedicated website page about [fires on mobile plant](#).

Refer to the position paper: [Fires-on-mobile-plant-position-paper-October-2019](#).



Roads or other vehicle operating areas: Two haul trucks collided nose to tail at an open cut coal mine. There was no evidence that the rear truck attempted to brake before the collision. The operator of the rear truck was found to have a mobile phone in the truck. Neither operator was injured.

While the cause of this incident is not yet known, mines are reminded of the need to monitor and enforce their policies regarding mobile phone usage. Strong consideration should be given to implementing technologies that continuously monitor and identify operator distraction, warning the operator via a tiered alarm system.



Ground or strata failure: At an open cut coal mine, localised cracking has occurred on a public road adjacent to its highwall. The mine notified the local council of the issue, and consequently the road was closed to the public. The mine had identified minor deterioration of the highwall several weeks prior to the cracking first being identified and had commenced stabilisation and remedial works. Resources Regulator inspectors attended the mine site and assessed the extent of the road cracks and the highwall deterioration, as well as the remedial works and monitoring implemented by the mine.

This situation is the subject of ongoing monitoring by the Resources Regulator. Mine operators are reminded that when developing the control measures to manage the risks of ground or strata failure, consideration must be given to:

- the means by which water may enter the mine, and the procedures for removing water from the mine and how those procedures influence rock stability over time and
- the geotechnical characteristics of the rocks and soil, including the effects of water on rock support and stability.

Work health and safety activities

Safety incident notifications

FIGURE 1. SAFETY INCIDENT NOTIFICATIONS RECEIVED BY SECTOR – MARCH 2019 TO MARCH 2020





TABLE 1. DETAILS OF SAFETY INCIDENTS WHERE INSPECTORS WERE DEPLOYED - MARCH 2020

DATE NOTIFIED	MINE TYPE	TRIAGE CLASSIFICATION	INCIDENT
5 March	Surface coal	Elevated	Cracking in the road pavement adjacent and to the north of the mine.
7 March	Surface coal	Elevated	Two vehicles collided nose to tail.
12 March	Surface coal	Elevated	Dump face of the windrow collapsed which has caused the dump and the truck to slump. Truck unable to be driven out under its own tractive power.
31 March	Underground coal	Elevated	Conveyor drive head gearbox anti run back failed which then caught fire. Flames were approx. 300mm high. The belt was shut down and two extinguishers were used to put out the fire.
Total			4

Safety assessments

Safety assessments commenced

FIGURE 2. SAFETY ASSESSMENT ACTIVITIES COMMENCED BY SECTOR - MARCH 2019 TO MARCH 2020



Proactive and reactive safety assessments

Proactive assessments include targeted assessments and planned inspections. Assessments conducted in response to incident notifications, targeted interventions, high risk activity notifications and action requests are reported as reactive assessments. In March 2020, 45% of all site and desktop safety assessments were proactive. Of the 163 site assessments conducted, almost 86% were proactive.

FIGURE 3. SAFETY ASSESSMENT ACTIVITIES BY CATEGORY AND NATURE - MARCH 2019 TO MARCH 2020





FIGURE 4. SAFETY SITE ASSESSMENT ACTIVITIES BY NATURE - MARCH 2019 TO MARCH 2020



Safety site targeted assessment program

Under its safety site targeted assessment program, the NSW Resources Regulator conducted 15 site-based assessments targeting three different hazards in March 2020.

FIGURE 5. TARGETED SAFETY SITE ASSESSMENTS - MARCH 2019 TO MARCH 2020





TABLE 2. DETAILS OF TARGETED SAFETY SITE ASSESSMENTS - MARCH 2020

HAZARD	SECTOR	MINE
Fire or explosion - Electrical Focus	Coal mines	Bulga Surface Operations
		Ravensworth Operations
Tailings Dams	Coal mines	Charbon Open Cut Coal Mine
		Glendell Open Cut
		Mt Arthur North - (incl CHPP)
		Stratford CHPP
		Ulan Surface Operations
		Wambo Coal Handling & Preparation Plant
		West Cliff Coal Preparation Plant
		Wilpinjong Coal Mine
Emergency Planning - Self Escape and Refuge	Large mines	Peak Gold Mine
		Tomingley Gold Mine
Fire and Explosion - Haz Chem, fire suppression and escape ways	Coal mines	Rixs Creek Mine
		Wambo Coal Handling & Preparation Plant
		Wambo Open Cut Coal Mine
TOTAL		15

Safety compliance activities

Safety notices issued

FIGURE 6. SAFETY NOTICES ISSUED BY NOTICE TYPE - MARCH 2019 TO MARCH 2020



Prohibition notices issued

In March 2020, 23 prohibition notices were issued under section 195 of the *Work Health and Safety Act 2011*.

TABLE 3. PROHIBITION NOTICES ISSUED – MARCH 2020

ISSUED TO PCBU*	MINE LOCATION	PROHIBITED ACTIVITY
Mudgee Dolomite & Lime Pty Ltd	Buckaroo Mine	Accessing the back deck of the excavator.
Hodgson Quarries and Plant Pty Ltd	Hodgson Quarries Pty Ltd - HB Maroota Quarry	Any person proceeding beyond the trucks external ladder at the back of the Mitsubishi water cart truck.
Hodgson Quarries and Plant Pty Ltd	Hodgson Quarries Pty Ltd - HB Maroota Quarry	Accessing the back deck of the Komatsu 400 and Hitachi 240 excavators.

ISSUED TO PCBU*	MINE LOCATION	PROHIBITED ACTIVITY
Hodgson Quarries and Plant Pty Ltd	Hodgson Quarries Pty Ltd - HB Maroota Quarry	<ol style="list-style-type: none"> 1. Any person proceeding beyond the door of the identified Volvo A 40D articulated dump truck (drivers' side), unless it is to enter cabin. 2. Any person using the ladder or truck platform on the identified Volvo A 40D articulated dump trucks (opposite side of cabin) to proceed up for any task.
BMR Quarries	Mount Winton Quarry	<ol style="list-style-type: none"> 1. Any person proceeding beyond the door of the identified Volvo A 40D articulated dump truck (drivers' side), unless it is to enter cabin. 2. Any person using the ladder or truck platform on the identified Volvo A 40D articulated dump trucks (opposite side of cabin) to proceed up for any task.
Inverell Aggregate Supplies Pty Ltd	Inverell Aggregate Supply Pty - Rifle Range Road 1	<p>This notice relates to the Komatsu WA500 front end loader unit 477 on site and requires the mine operator to allow:</p> <p>No person to undertake maintenance activities along the front walkways on both sides of the operator's cabin.</p>
Inverell Aggregate Supplies Pty Ltd	Inverell Aggregate Supply Pty – Rifle Range Road 1	<p>This notice relates to the Caterpillar 769C haul truck on site and requires the mine operator to allow:</p> <p>No person is to use the cabin platform on the identified truck (driver's access side of cabin) to proceed up for any task unless it is to enter the cabin.</p>
Springvale Coal Pty Limited	Springvale Mine Underground Operation	Operating the Domino Pet service vehicles at the Springvale Mine Underground Operation.
Charbon Coal Pty Limited	Charbon Open Cut Coal Mine	Tipping material directly into reject emplacement cells/ponds.
Aurelia Metals Limited	Hera Mine	Installing any handheld ladder rises between the 535 and 510 levels by the handheld ladder rising method.
Newcrest Mining Limited	Cadia East Project	Using the Caterpillar 3000 Loader 108 in service until the cause of the unintended movement has been determined and all faults have been repaired and tested to confirm correct operation.
Mark Powell	MC34975	Raising or lowering persons on this conveyance.
Hanson Construction Materials Pty Ltd	Wagga Quarry	Accessing the scaffolding installed on to screen plant 4.
Hanson Construction Materials Pty Ltd	Wagga Quarry	Accessing the platform on screen plant 4.
Craig Williams	Pinnacle Mines	Carrying out work on site by the electrical contractor's workers (Vertex Power & Process).

ISSUED TO PCBU*	MINE LOCATION	PROHIBITED ACTIVITY
Burmix Concrete P/L	Tarcoola	<ol style="list-style-type: none"> 1. Operating the old Terex 683 screen. 2. Accessing walkways on the old Terex 683 screen.
Murcury Group Pty Ltd trading as Supermix Concrete	Eunony Bridge Road quarry	<ol style="list-style-type: none"> 1. Workers proceeding beyond the front of the door on the driver's door side of the Volvo A30D articulated dump truck 2. Workers accessing the off-driver's side door side (left hand side when viewing the plant from the front) of the Volvo A30G articulated dump truck.
Murcury Group Pty Ltd trading as Supermix Concrete	Eunony Bridge Road quarry	<ol style="list-style-type: none"> 1. Workers proceeding beyond the front of the door on the driver's door side of the Volvo A40G articulated dump truck 2. Workers accessing the off-driver's door side (left hand side when viewing the plant from the front) of the Volvo A40G articulated dump truck.
Nicholas Casement	MC45914	Entering the past area where current working drive has broken into older workings.
Peak Gold Mines Pty Limited	Peak Gold Mine	Using the men and materials shaft winding system. The following activities are except from the prohibition: Using the winding system for the purposes of investigation of the incident, implementing corrective actions and verifying correct operation of the winding system. Personnel shall not be transported in any conveyance associated with the winding system during the exempted activities.
Hanson Construction Materials Pty Ltd	Wagga Quarry	Accessing onto CV110 conveyor.
Craig Williams	Pinnacle Mines	Conducting lead risk work if most recent health monitoring shows that the worker's blood lead level is, or is more than— (i) for females not of reproductive capacity and males—30 _{µg} /dL (1.45 _{µmol} /L), or (ii) for females of reproductive capacity—10 _{µg} /dL (0.48 _{µmol} /L),
Burmix Concrete P/L	Tarcoola	<p>This notice relates to the Caterpillar 730 Articulated dump truck on site and requires the mine operator to:</p> <ol style="list-style-type: none"> 1. Proceeding beyond the door of the identified articulated dump truck (drivers' side), unless it is to enter cabin. 2. Using the ladder or truck platform on the identified articulated dump trucks (opposite side of cabin) to proceed up for any task.
TOTAL		23


* Person conducting business or undertaking

Safety mining competencies activities

Competence and practising certificates granted

Safety mining competence activities include certificate of competence (mutual recognition). In March 2020, 34 practising certificates and four practising certificates for mutual recognition were granted.


FIGURE 7. COMPETENCE AND PRACTISING CERTIFICATES GRANTED - MARCH 2019 TO MARCH 2020



Safety mining authorisation activities

Safety mining authorisations include licence applications to carry out prescribed high-risk activities, plant item registrations, design registration and exemptions. During March 2020, seven licences and 138 plant item registrations were granted.

FIGURE 8. MINING AUTHORISATIONS GRANTED - MARCH 2019 TO MARCH 2020



High risk activity notifications

In March 2020, the NSW Resources Regulator received 11 high risk activity notifications under clause 33 of the Work Health and Safety (Mines and Petroleum Sites) Regulation 2014.

FIGURE 9. HIGH RISK ACTIVITY NOTIFICATIONS BY ENGINEERING DISCIPLINE – MARCH 2020 TO MARCH 2020




TABLE 4. HIGH RISK ACTIVITY NOTIFICATIONS RECEIVED – MARCH 2020

MINE	LEGISLATION*	TYPE OF NOTIFICATION	NO.
Mount Thorley Warkworth Operations	Schedule 3 Clause 35	The establishment, operation, alteration or decommissioning of a tailing’s storage facility.	1
Mandalong Mine	Schedule 3 Clause 15	The formation of a pillar other than a conforming pillar.	1
Bulga Surface Operations	Schedule 3 Clause 27	The establishment, operation, alteration or decommissioning of an emplacement area.	1
Baal Bone Underground	Schedule 3 Clause 27	The establishment, operation, alteration or decommissioning of an emplacement area.	1
CSA Mine	Schedule 3 Clause 4	Development of a new mine entry (including by sinking a shaft or drift or raise boring).	1
Moolarben Coal Operations - Underground	Schedule 3 Clause 10	Sealing (other than emergency sealing), but only if notice has not been given as part of a notice for secondary extraction.	1
PPL0004 Menangle Park 13	Schedule 3 Clause 32	Decommissioning a well.	1

MINE	LEGISLATION*	TYPE OF NOTIFICATION	NO.
PPL0001 Johndilo 11	Schedule 3 Clause 32	Decommissioning a well.	1
Ulan West Operations	Schedule 3 Clause 11	The conduct of hot work in a hazardous zone.	1
Moolarben Coal Operations - Underground	Schedule 3 Clause 16(1)(a)	Secondary extraction by longwall mining, short wall mining or miniwall mining.	1
North Wambo Underground	Schedule 3 Clause 7(2)(a)	Working in inrush control zone - potential source of inrush can be inspected.	1
TOTAL			11


* Work Health and Safety (Mines and Petroleum Sites) Regulation 2014

Mining Act regulatory activities

Mining Act statutory notices

In March 2020, the NSW Resources Regulator issued eight statutory notices under the *Mining Act 1992*.

FIGURE 10. MINING ACT STATUTORY NOTICES ISSUED BY NOTICE TYPE - MARCH 2019 TO MARCH 2020



In March 2020, eight notice of directions were issued under section 240 of the *Mining Act 1991*.

TABLE 5. NOTICES OF DIRECTIONS ISSUED DETAILS - MARCH 2020


ISSUED TO	LOCATION	SECTION 240 OF THE <i>MINING ACT 1992</i> DIRECTION
Claypave Pty Ltd	ML1240 (Act 1973)	Rehabilitate the land at the mine known as Claypave - Coombell Road Cattle Yard located at Lot 1/DP1174724 that is affected by activities under Mining Lease 1240 (Mining Act 1973) (ML1240).
		Submit a final Rehabilitation Report prepared by a suitably qualified and experienced person, providing evidence of completion of rehabilitation work.
Col'doro Mining Pty Ltd		Prepare and submit a Mining Operations Plan in accordance with the ESG3: Mining Operations Plan (MOP) Guidelines, September 2013.
Jack Pocock	MC59201	<ul style="list-style-type: none"> Repair all areas of subsidence, slumping and cracking on MC59201, and make all landforms safe and stable. Repair and make stable all areas on MC59201 which are exhibiting erosion. Reshape and stabilise all disturbed areas on MC59201 to ensure it is adequately drained and protected from further subsidence and erosion.
Individual	MC49668 and MC49669	<ul style="list-style-type: none"> Rehabilitate MC49668 and MC49669 in accordance with the Department guidelines and standards. Remove all rubbish from MC49668 and MC49669 dispose of in a recognised public rubbish facility. Remove all un-roadworthy vehicles, caravans, trailers and miscellaneous equipment from MC49668 and MC49669. Remove the mullock and white dirt from the surface of the MC49668 and MC49669 and dispose of at an appropriate waste facility.
Mount Thorley Operations Pty Limited		Submit an updated Mining Operations Plan prepared in accordance with the applicable MOP guidelines. The MOP must be accompanied by a Rehabilitation Cost Estimate (RCE) for the Authorisations prepared in accordance with the Department Guideline ESG1: Rehabilitation Cost Estimate Guidelines (June 2017) and utilise the Departments Rehabilitation Cost Estimation Tool (May 2019). The MOP and RCE are to be submitted to the Regulator.
Individual	MPL341	<p>Rehabilitate all surface disturbances associated with activities conducted on MPL 341 to the satisfaction of the Minister.</p> <ul style="list-style-type: none"> This includes but is not limited to removal of all buildings, machinery, rubbish and agitators, removal of all mullock to an approved mullock dump, silt dam bund walls are to be made stable and the surface of silt covered with soil. The final surface shaped, ripped, and vegetation spread across the surface and seeded.

ISSUED TO	LOCATION	SECTION 240 OF THE <i>MINING ACT 1992</i> DIRECTION
Individual	MC49938	Remove the stockpile of mullock observed on the surface of MC49938 and take it to a licensed mullock dump.
Warkworth Mining Ltd		Submit an updated Mining Operations Plan for the Mount Thorley Warkworth Mine prepared in accordance with the applicable MOP guidelines. The MOP must be accompanied by a Rehabilitation Cost Estimate (RCE) for the Authorisations prepared in accordance with the Department Guideline ESG1: Rehabilitation Cost Estimate Guidelines (June 2017) and utilise the Departments Rehabilitation Cost Estimation Tool (May 2019). The MOP and RCE are to be submitted to the Regulator.
TOTAL		8

Security deposit reviews

In March 2020, the NSW Resources Regulator completed 28 exploration and mining rehabilitation security deposit reviews under the *Mining Act 1992*. A review of security deposits is undertaken when an authorisation holder applies to vary approved activities.

FIGURE 11. SECURITY DEPOSIT REVIEWS COMPLETED – MARCH 2019 TO MARCH 2020




Safety legislation and Mining Act notified compliance concerns

The NSW Resources regulator uses a variety of enforcement tools under work health and safety legislation and the *Mining Act 1992* to ensure compliance. The approach taken depends on the significance and impacts of the breach, the tools available under the legislation and the NSW Resources Regulator’s [compliance and enforcement approach](#).

Safety compliance concerns

In March 2020, there were no compliance concern (alleged breaches) determined under the Work Health and Safety (Mines and Petroleum Sites) legislation.

FIGURE 12. SAFETY LEGISLATION COMPLIANCE CONCERN ALLEGATION BREACHES SUSTAINED BY REGULATORY RESPONSE MARCH 2019 TO MARCH 2020



Mining Act compliance concerns

In March 2020, the NSW Resources Regulator found 27 compliance concerns (alleged breaches) under the *Mining Act 1992* to be sustained, resulting in the issuing of two penalty infringement notices, 21 official cautions and four requiring no further action. Details are listed below under key enforcement actions.

FIGURE 13. MINING ACT 1992 COMPLIANCE CONCERN ALLEGATION BREACHES SUSTAINED BY REGULATORY RESPONSE MARCH 2019 TO MARCH 2020




TABLE 6. KEY MINING ACT ENFORCEMENT ACTIONS – MARCH 2020

DATE	ENTITY	AUTHORITY	ACTON	AMOUNT	DETAILS
4 March	Ulan Stone Pty Ltd	ML1726	Penalty Notice	\$2,500	Breach of condition of authorisation (s.378D) by failing to comply with commitments in the Mining Operation Plan.
24 March	GFM Exploration Pty Ltd	EL8416	Penalty Notice	\$2,500	Breach of condition of authorisation (s.378D) by failing to comply with activity approval.
23 March	Aus Gold Pty Ltd	ML1322, EL8697 & EL8716	Deferment of proposed decision to cancel	N/A	ML1322 currently suspended.
TOTAL					3

Industry engagement activities

The NSW Resources Regulator's industry engagement activities for March 2020 are outlined below.

Committees and other industry body involvement

In March 2020, the NSW Resources Regulator participated in the following committees and working groups.

TABLE 7. COMMITTEES AND OTHER INDUSTRY BODY INVOLVEMENT - MARCH 2020

DATE	COMMITTEE/BODY	DETAIL
2 March	Standards Association	AS4024.3611 - mining exemptions written into standard.ISO14122 - adoption and variations with AS165.
3 March	Industry committee	Update of working group - Good maintenance practices, fire systems and suppression equipment design.
5 March	Local Emergency Management Committee	Muswellbrook- Singleton LEMC. SES negotiating with Mt. Arthur Coal on dam break scenarios.
5 March	Tailings Dam Safety	Workshop with Department of Planning, Environment Protection Authority and Resources Regulator.
5 March	Australian Standard AS/NZS2290.1.	Australian Standards working group for EL-023-04.
5 March	NSW Mine safety Advisory Committee (MSAC)	Quarterly meeting.
11 March	Subsidence Advisory NSW	Discuss regulatory interactions.
24 March	Dam Safety Committee	Dam Safety NSW.
25 March	Hunter Region Emergency Management Committee (Video Conference)	COVID-19 briefing.
25 March	Earthmoving Equipment Australian Standard Committee	ME-063
26 March	Standards Association	AS5062
26 March	Local Emergency Management Committee (Video Conferencing)	Orange-Cabbone LEMC: COVID-19 briefing.
26 March	Local Emergency Management Committee (Video Conferencing)	Broken Hill LEMC: COVID-19 briefing.

DATE	COMMITTEE/BODY	DETAIL
26 March	Local Emergency Management Committee (Video Conferencing)	Muswellbrook LEMC: COVID-19 briefing.
27 March	Local Emergency Management Committee (Video Conferencing)	Mudgee LEMC: COVID-19 briefing.
27 March	University of Queensland – Research Summit	Participation in the research summit held at UQ (via Zoom) looking at human aspects of automation and new technologies in mining.
31 March	Local Emergency Management Committee (Video Conferencing)	Narrabri Shire LEMC: COVID-19 briefing.
TOTAL		17

External education and engagement activities

TABLE 8. WORKSHOPS AND INFORMATION SESSIONS - MARCH 2020

DATE	TYPE OF ACTIVITY	LOCATION	DETAIL
5 March	Oral examinations	Maitland	Mining engineering manager and open cut examiner mines other than underground mines. 24 candidates.
10 March	Consultation forum	Penrith	WHS (MPS) Laws statutory review public consultation. 21 attendees.
11 March	Consultation forum	Wagga Wagga	WHS (MPS) Laws statutory review public consultation. 15 attendees.
12 March	Consultation forum	Wollongong	WHS (MPS) Laws statutory review public consultation. 10 attendees.
18 March	Stakeholder consultation	Lightning Ridge Miners Association - Teleconference	WHS (MPS) Laws statutory review stakeholder consultation.
18 March	Consultation forum	Dubbo	WHS (MPS) Laws statutory review public consultation. 12 attendees.
19 March	Consultation forum	Broken Hill	WHS (MPS) Laws statutory review public consultation. 6 attendees.

DATE	TYPE OF ACTIVITY	LOCATION	DETAIL
23 March	Consultation forum	Public web conference	WHS (MPS) Laws statutory review public consultation. 9 online attendees.
24 March	Consultation forum	Public web conference	WHS (MPS) Laws statutory review public consultation. 15 online attendees.
26 March	Exam briefing	Zoom video link	Presentation to candidates for mining engineering manager underground coal mines written and oral examination. 16 Candidates.
TOTAL			10

Publications and alerts

In March 2020, the NSW Resources Regulator published two safety alerts, one position paper, a guide for enforceable undertakings, a factsheet and policy for engagement and public consultation on our website.

TABLE 9. MEDIA RELEASES, SAFETY BULLETINS AND PUBLICATIONS MARCH 2020

DATE	TYPE	SUMMARY
02 March	Video	Lateral load video
02 March	Report	MSAC annual report 2018-2019
02 March	Form	Request for mine survey plans
05 March	Safety Alert	SA20-03 Tailgate hits worker's head
04 March	Gazette	GDA94 exemption
06 March	Weekly Incident Summary	Week ending 28 February
06 March	Mine Safety News	Join our team
11 March	Report	Quarterly Report Oct - Dec 2019
12 March	Mine Safety News	Mine Safety News
12 March	Form	AD17 Application for review of assessed security deposit (PDF and fillable form)
12 March	Weekly Incident Summary	Week ending 6 March
13 March	Gazette	Publish gazette: Ancillary Reports – Fire related to mobile plant 2020
17 March	Report	Business Activities Overview 2018 - 2019

DATE	TYPE	SUMMARY
17 March	Report	Business Activities Overview 2019
19 March	Weekly Incident Summary	Week ending 13 March 2020
25 March	Safety Alert	SA20-04 COVID-19 related worker complaints/Mine Safety News Safety alert
27 March	Guide	Enforceable undertakings guide
26 March	Minutes	MSAC Minutes 5 December 2019
26 March	Mine Safety News	Mine Safety News
27 March	Weekly Incident Summary	Week ending 20 March 2020
27 March	Gazette	Tier3 Quarry Manager Class Exemption March 2020
27 March	Factsheet	Quarry Manager exemption (Tier 3)
27 March	Position paper	Position paper: Revision to silica exposure standard
31 March	Policy	Engagement and public consultation policy
TOTAL		24