

Mine Safety

SAFETY BULLETIN

Injuries incurred from falling plant

INCIDENT

The number of workers becoming injured after falling from mobile and fixed plant is increasing.

Plant involved in these incidents include: large earth moving machines, small fixed and transportable conveyors, bobcat-type loaders, site delivery trucks and underground mining machines.

Injuries from the impact of the fall include leg/ankle sprains, strains and fractures, collar bone dislocations, skull fractures, back injuries, arm and rib fractures.

CIRCUMSTANCES

Circumstances contributing to these incidents include accessing and egressing mobile and fixed plant on steps, ladders and walkways, as well as working on platforms and landings.

There have also been several incidents where injuries occurred when covering loads and unloading road registered trucks.

INVESTIGATION

Investigations identified a number of contributory factors, including:

- insufficient access walkways, stairways, steps and hand rails
- inadequate maintenance of access walkways, stairways, steps and hand rails
- slippery, wet or worn surfaces caused by environmental conditions
- Inappropriate systems of work for maintenance activities or covering loads
- tasks considered to be low risk left to human behaviour
- a lack of operator supervision
- task-specific work equipment such as stairs, stands or mobile work platforms not considered necessary
- inadequate identification of the hazards associated with working at heights.

SPECIFIC LEGISLATION

Safety Bulletin No: 16-06 File number: PUB16/540 Phone: 1300 814 609 Date Published: 22 December 2016 The following clauses of the Work Health and Safety Regulation 2011 set out mandatory requirements for a person conducting a business or undertaking an activity at a workplace:

- clause 78 Management of risk of fall
- clause 79 Specific requirements to minimise risk of fall.

The NSW code of practice, *Managing risks of falls in workplaces*, provides guidance on complying with the WHS regulation in relation to falls.

RECOMMENDATIONS

Designers, manufacturers, suppliers and users of mobile plant should consider:

- the NSW code of practice: Managing risks of falls in workplaces
- how to carry out routine activities without risk of fall, such as cleaning, inspections, monitoring, and adjustments, so far as is reasonably practicable
- the relevant standards when installing steps, ladders, walkways, cabin access and egress, work platforms and other landings
- using three-point contact
- providing adequate training, supervision and task observation for site practices.

FURTHER INFORMATION

- AS/NZS 1657 Fixed platforms, walkways, stairways and ladders-design, construction and installation
- AS 3868 Earth-moving machinery Design guide for access systems
- ISO 2687 Earth-moving machinery Access systems
- ISO 14122 Safety of machinery Permanent means of access to machinery
 - Part 1: Choice of fixed means of access between two levels
 - Part 2: Working platforms and walkways
 - Part 3: Stairs, stepladders and guard-rails
 - Part 4: Fixed ladders
- MDG 15 Mining design guideline Mobile and transportable plant for use at mines (other than underground coal mines)
- NSW code of practice: Mechanical engineering control plan
- http://www.dmp.wa.gov.au/Safety/Hazard-awareness-videos-16435.aspx

NOTE: Ensure all relevant people in your organisation receive a copy of this Safety Bulletin, and are informed of its content and recommendations. This Safety Bulletin should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's notice board.

Issued by

Dave McLean Chief Inspector of Mines Appointed pursuant to Work Health & Safety (Mines) Act 2013

View more safety alerts and search our safety database at www.resources.nsw.gov.au/miners-and-explorers/safety-and-health/safety-alerts. If you would like to receive safety alerts by email, enter your contact details at www.resources.nsw.gov.au/info/signup.

Disclaimer

The information contained in this publication is based on knowledge and understanding at the time of writing. However, because of advances in knowledge, users are reminded of the need to ensure that information on which they rely is up to date and to check the currency of the information with the appropriate officer of NSW Department of Industry or the user's independent advisor.