## **Resources Regulator**

Department of Regional NSW



## Register of licences for repairing of flexible reeling, feeder or trailing cables for use in a hazardous zone

(Current as of 16 April 2024)

Licence holder	Licence holder ACN	Licence holder address	Licensed facility address	Licence number	Issue date	Expiry date	Certification	Licence status
ATF Mining Electrics Pty Ltd Trading as: Ampcontrol Illawarra	001 175 435	21 Old Punt Road, TOMAGO NSW 2322	30 Investigator Drive UNANDERRA 2526	MLA 078963	20 October 2023	19 October 2028	License Assessment: Department Regional NSW, Resources Regulator – Assessment Report No. EvtNot0018436, dated 21 September 2023	Active
ATF Mining Electrics Pty Ltd Trading as: Ampcontrol Thornton	001 175 435	118 Glenwood Drive THORNTON NSW 2322	118 Glenwood Drive THORNTON NSW 2322	MLA 078035	20 March 2023	19 March 2028	License Assessment: Department of Regional NSW, Resources Regulator – Assessment Report, dated 8 March 2023	Active
JTMEC Pty Ltd	114 937 245	50 Boulder Rd MALAGA WA 6090	6 Corporation Place ORANGE NSW 2800	MLA 140986	24 March 2023	23 March 2028	Licence Assessment: Department of Planning & Environment, Resources Regulator – Assessment Report, dated 30 August 2022	Active
KableX Pty Ltd	169 665 178	2/82 Callemondah Drive GLADSTONE QLD 4680	6 Magpie Street McDOUGALLS HILL NSW 2330	MLA 0001931	4 August 2022	3 August 2025	Licence Assessment: Department of Planning & Environment, Resources Regulator – Assessment Report, dated 20 April 2022	Active
PBE Rutherford Mining Pty Ltd	622 492 826	3 Kilcoy Drive TOMAGO NSW 2322	59 Clwydd Street LITHGOW NSW 2790	MLA 18164	9 March 2024	8 June 2024	Licence Assessment: Department of Regional NSW, Resources Regulator – Assessment Report No. EvtNot0011456, dated 4 March 2021	Active

RDOC23/250396 1

## Register of licences for repairing of flexible reeling, feeder or trailing cables for use in a hazardous zone

Licence holder	Licence holder ACN	Licence holder address	Licensed facility address	Licence number	Issue date	Expiry date	Certification	Licence status
PBE Rutherford Mining Pty Ltd	622 492 826	3 Kilcoy Drive TOMAGO NSW 2322	3 Kilcoy Drive TOMAGO NSW 2322	MLA 18165	23 June 2023	22 June 2028	License Assessment: Department of Regional NSW, Resources Regulator – Assessment Report No. EvtNot0017633, dated 1 June 2023	Active

<sup>©</sup> State of New South Wales through Regional NSW 2024. The information contained in this publication is based on knowledge and understanding at the time of writing (April 2024). However, because of advances in knowledge, users are reminded of the need to ensure that the information upon which they rely is up to date and to check the currency of the information with the appropriate officer of the Regional NSW or the user's independent adviser.

RDOC23/250396 2